




CHRISTOPHER MILLS CONSERVATION SERVICES, LLC

Johnston, Felton, Hay House/ Macon Georgia c.1860

Recovered, Conserved and Recreated 19th century finishes 2019-20

Woodgraining stair walls, Floor design, Painted walls and woodwork

Contact: Jonathan Poston, Director of Historic Preservation
William Graham, Historic Consultant




Conditions before treatment




During floor restoration



During floor restoration





Overpaint removal to recover original graining




Original graining left, 2nd graining overpaint right



Cornice restoration




Recreating woodgraining



Mock-up of intended marblizing and woodgraining



Hall walls and doors after treatment



After Treatment